



UMPQUA Research Company

626 NE Division St. - P.O. Box 609
 Myrtle Creek, Oregon 97457
 (541) 863-5201 Fax: (541) 863-6199
 E-mail: Lab@URCmail.net
 Internet: http://ChemLab.cc
 ORELAP ID# OR100031

ANALYSIS REPORT

URC # 4031436

Pendleton School District	Project: General	Date Reported: 03/26/24
107 NW 10th Street	Project #: PHS Gold Gym Lead Testing	Date Received: 03/13/24 11:00
Pendleton, OR 97801	Client Contact: Michelle Jones	Sampled By: Thad Baum

Method: USEPA 200.8

Matrix: Drinking Water

	Sample Location	Code	Result	Units	MRL	MCL	Sampled	Analyzed	Analyst	Qualifier
4031436-01	Sample Location: 22070501-071BF/ Gold Gym Mens Upstairs Restroom Sink 1146									
	Lead (‡)	1030	ND	ppb	1.0	15	03/08/24 09:40	03/21/24	DST	
4031436-02	Sample Location: 22070501-072BF/ Gold Gym Womens Upstairs Sink 1144 / Restroom Sink-1									
	Lead (‡)	1030	2.3	ppb	1.0	15	03/08/24 09:40	03/21/24	DST	
4031436-03	Sample Location: 22070501-073DW/ Gold Gym Upstairs East Side 1143 / Drinking Fountain									
	Lead (‡)	1030	ND	ppb	1.0	15	03/08/24 09:44	03/21/24	DST	
4031436-04	Sample Location: 22070501-074WB/ Gold Gym Upstairs East Side 1143 / Water Bottle Filler									
	Lead (‡)	1030	ND	ppb	1.0	15	03/08/24 09:44	03/21/24	DST	
4031436-05	Sample Location: 22070501-075BF/ Gold Gym Girls Dressing Rm 1136 / Left Restroom Sink-1									
	Lead (‡)	1030	ND	ppb	1.0	15	03/08/24 09:42	03/21/24	DST	
4031436-06	Sample Location: 22070501-076BF/ Gold Gym Girls Dressing Rm 1136 / Right Restroom Sink-2									
	Lead (‡)	1030	ND	ppb	1.0	15	03/08/24 09:42	03/21/24	DST	
4031436-07	Sample Location: 22070501-077DW/ Gold Gym Upstairs West Side 1131 / Drinking Fountain									
	Lead (‡)	1030	ND	ppb	1.0	15	03/08/24 09:36	03/21/24	DST	
4031436-08	Sample Location: 22070501-078WB/ Gold Gym Upstairs West Side 1131 / Water Bottle Filler									
	Lead (‡)	1030	ND	ppb	1.0	15	03/08/24 09:36	03/21/24	DST	
4031436-09	Sample Location: 22070501-079BF/ Gold Gym Boys Single Restroom Sink 1126B									
	Lead (‡)	1030	1.1	ppb	1.0	15	03/08/24 09:30	03/21/24	DST	
4031436-10	Sample Location: 22070501-080BF/ Gold Gym Boys Office Restroom Sink 1113									
	Lead (‡)	1030	4.1	ppb	1.0	15	03/08/24 09:33	03/21/24	DST	
4031436-11	Sample Location: 22070501-081BF/ Gold Gym Boys Dressing Room 1124 / Left Restroom Sink-1									
	Lead (‡)	1030	ND	ppb	1.0	15	03/08/24 09:25	03/21/24	DST	
4031436-12	Sample Location: 22070501-082BF/ Gold Gym Boys Dressing Room 1124 / Right Restroom Sink-2									
	Lead (‡)	1030	ND	ppb	1.0	15	03/08/24 09:25	03/21/24	DST	

UMPQUA Research Company/MC

The results in this report apply to the samples analyzed in accordance with the chain of custody document.

This analytical report must be reproduced in its entirety.

Dan Phillips, Laboratory Manager



UMPQUA Research Company

626 NE Division St. - P.O. Box 609
Myrtle Creek, Oregon 97457
(541) 863-5201 Fax: (541) 863-6199
E-mail: Lab@URCmail.net
Internet: <http://ChemLab.cc>
ORELAP ID# OR100031

ANALYSIS REPORT

URC # 4031436

Qualifiers and Definitions

DET	Analyte DETECTED
ND	Analyte NOT DETECTED at or above the MRL (minimum reporting limit)
NA	Not Applicable
NR	Not Reported
dry	Sample results reported on a dry weight basis
RPD	Relative Percent Difference
MRL	Minimum Reporting Limit
MDL	Minimum Detection Limit
MCL	Maximum Contamination Level
(‡)	ORELAP Accredited Analyte
(~)	Due to rounding of individual analytes, the "total" may vary slightly from the sum of the individual analyte values.

UMPQUA Research Company/MC

The results in this report apply to the samples analyzed in accordance with the chain of custody document.

This analytical report must be reproduced in its entirety.

Dan Phillips, Laboratory Manager