

Lead in Water Test Results Summary: Administration


Notes:

- The lead in water **Action Level is 15 parts per billion (ppb)**.
Any fixture testing at or above the action level of 15 ppb is immediately removed from service and cannot be returned to service until it has been remediated and passed follow-up testing.
- A "ND" or "non-detect" test result indicates the sample measured below the minimum detection limit of [#] ppb.

Legend:

- Test results **equal to or greater than the Action Level** of 15 ppb are **highlighted in red and precede a "High" value** in the "Initial Level" or "Final Level" column.
- Test results **near the Action Level** of 15 ppb (11.99 to 14.99 ppb) are **highlighted in yellow and precede a "Med" (Medium) value** in the "Initial Level" or "Final Level" column.

Fixture Location Description	Fixture ID #	Initial Test Date	Initial Test Result (ppb)	Initial Level	Final Retest Date	Final Test Result (ppb)	Final Level
CONFERENCE ROOM STAFF SINK	22070000-001SF	3/6/2024	ND	Low	[enter date]	[enter result]	[autofill]
CONFERENCE ROOM DRINKING FOUNTAIN	22070000-002DW	3/6/2024	ND	Low			
BOARD ROOM SINK	22070000-003SF	3/6/2024	1.1	Low			
MAIN HALLWAY DRINKING FOUNTAIN	22070000-004DW	3/6/2024	ND	Low			
MAIN HALLWAY BOTTLE FILLER	22070000-005WB	3/6/2024	ND	Low			
NORTH MEN'S RESTROOM - LEFT SINK	22070000-006BF	3/6/2024	ND	Low			
NORTH MEN'S RESTROOM - RIGHT SINK	22070000-007BF	3/6/2024	ND	Low			
MAIN HALLWAY RESTROOM SINK	22070000-008BF	3/6/2024	6.7	Low			
STAFF BREAKROOM RESTROOM SINK - COLD SIDE	22070000-009BF	3/6/2024	ND	Low			
STAFF BREAKROOM WATER COOLER	22070000-010WC	3/6/2024	ND	Low			
STAFF BREAKROOM SINK	22070000-011SF	3/6/2024	ND	Low			
FINGERPRINTING ROOM SINK	22070000-012SF	3/6/2024	1.2	Low			
WOMEN'S RESTROOM - LEFT SINK	22070000-013BF	3/6/2024	ND	Low			
WEST WOMEN'S RESTROOM - RIGHT SINK	22070000-014BF	3/6/2024	ND	Low			
MAINTENANCE RESTROOM SINK	22070000-015BF	3/6/2024	ND	Low			
MAINTENANCE BREAKROOM SINK	22070000-016SF	3/6/2024	ND	Low			
MAINTENANCE BREAKROOM WATER COOLER	22070000-017WC	3/6/2024	ND	Low			
MAINTENANCE SHOP ICE MACHINE	22070000-018IM	3/6/2024	ND	Low			
MAINTENANCE SHOP SINK	22070000-019SF	3/6/2024	ND	Low			
106 BOY'S RESTROOM-DOWNSTAIRS - LEFT SINK	22070000-020BF	3/6/2024	2.2	Low			
106 BOY'S RESTROOM-DOWNSTAIRS - RIGHT SINK	22070000-021BF	3/6/2024	8.2	Low			
108 GIRL'S RESTROOM-DOWNSTAIRS SINK	22070000-022BF	3/6/2024	ND	Low			
STAFF BREAKROOM RESTROOM SINK - HOT SIDE	22070000-023BF	3/6/2024	ND	Low			



UMPQUA Research Company

626 NE Division St. - P.O. Box 609
Myrtle Creek, Oregon 97457
(541) 863-5201 Fax: (541) 863-6199
E-mail: Lab@URCmail.net
Internet: http://ChemLab.cc
ORELAP ID# OR100031

ANALYSIS REPORT

URC # 4031331

Pendleton School District
107 NW 10th Street
Pendleton, OR 97801

Project: General
Project #: District Office Lead Testing
Client Contact: Michelle Jones

Date Reported: 03/21/24
Date Received: 03/13/24 11:00
Sampled By: Thad Baum

Method: USEPA 200.8


Matrix: Drinking Water


	Sample Location	Code	Result	Units	MRL	MCL	Sampled	Analyzed	Analyst	Qualifier
4031331-01	Sample Location: 22070000-001SF / Conference Room 228 / Staff Sink									
Lead (†)		1030	ND	ppb	1.0	15	03/06/24 06:36	03/20/24	DST	
4031331-02	Sample Location: 22070000-002DW/ Conference Room 228 / Drinking Fountain									
Lead (†)		1030	ND	ppb	1.0	15	03/06/24 06:36	03/20/24	DST	
4031331-03	Sample Location: 22070000-003SF/ Board Room 226 / Staff Sink									
Lead (†)		1030	1.1	ppb	1.0	15	03/06/24 06:37	03/20/24	DST	
4031331-04	Sample Location: 22070000-004DW/ North Hallway 227 / Drinking Fountain									
Lead (†)		1030	ND	ppb	1.0	15	03/06/24 06:38	03/20/24	DST	
4031331-05	Sample Location: 22070000-005WB/ North Hallway 227 / Water Bottle Filler									
Lead (†)		1030	ND	ppb	1.0	15	03/06/24 06:38	03/20/24	DST	
4031331-06	Sample Location: 22070000-006BF/ North Men's Restroom 224 / Bathroom Sink #1									
Lead (†)		1030	ND	ppb	1.0	15	03/06/24 06:39	03/20/24	DST	
4031331-07	Sample Location: 22070000-007BF/ North Men's Restroom 224 / Bathroom Sink #2									
Lead (†)		1030	ND	ppb	1.0	15	03/06/24 06:39	03/20/24	DST	
4031331-08	Sample Location: 22070000-008BF/ Main Co-ed Restroom 204 / Bathroom Sink									
Lead (†)		1030	6.7	ppb	1.0	15	03/06/24 06:40	03/20/24	DST	
4031331-09	Sample Location: 22070000-009BF/ Staff Breakroom Restroom 207 / Bathroom Sink Cold									
Lead (†)		1030	ND	ppb	1.0	15	03/06/24 06:41	03/20/24	DST	
4031331-10	Sample Location: 22070000-010WC/ Staff Breakroom 206 / Water Cooler									
Lead (†)		1030	ND	ppb	1.0	15	03/06/24 06:42	03/20/24	DST	
4031331-11	Sample Location: 22070000-011SF/ Staff Breakroom 206 / Staff Sink									
Lead (†)		1030	ND	ppb	1.0	15	03/06/24 06:43	03/20/24	DST	
4031331-12	Sample Location: 22070000-012SF/ Fingerprinting Room 218 / Staff Sink									
Lead (†)		1030	1.2	ppb	1.0	15	03/06/24 06:44	03/20/24	DST	

UMPQUA Research Company/MC

The results in this report apply to the samples analyzed in accordance with the chain of custody document.

This analytical report must be reproduced in its entirety.


Dan Phillips, Laboratory Manager



UMPQUA Research Company

626 NE Division St. - P.O. Box 609
Myrtle Creek, Oregon 97457
(541) 863-5201 Fax: (541) 863-6199
E-mail: Lab@URCmail.net
Internet: <http://ChemLab.cc>
ORELAP ID# OR100031

ANALYSIS REPORT

URC # 4031331

Method: USEPA 200.8


Matrix: Drinking Water

	Sample Location	Code	Result	Units	MRL	MCL	Sampled	Analyzed	Analyst	Qualifier
4031331-13	Sample Location: 22070000-013BF/ West Women's Restroom 216 / Bathroom Sink #1									
Lead (‡)		1030	ND	ppb	1.0	15	03/06/24 06:45	03/20/24	DST	
4031331-14	Sample Location: 22070000-014BF/ West Women's Restroom 216 / Bathroom Sink #2									
Lead (‡)		1030	ND	ppb	1.0	15	03/06/24 06:45	03/20/24	DST	
4031331-15	Sample Location: 22070000-015BF/ Maintenance Restroom 244 / Bathroom Sink									
Lead (‡)		1030	ND	ppb	1.0	15	03/06/24 06:47	03/20/24	DST	
4031331-16	Sample Location: 22070000-016SF/ Maintenance Breakroom 243 / Staff Sink									
Lead (‡)		1030	ND	ppb	1.0	15	03/06/24 06:48	03/20/24	DST	
4031331-17	Sample Location: 22070000-017WC/ Maintenance Breakroom 243 / Water Cooler									
Lead (‡)		1030	ND	ppb	1.0	15	03/06/24 06:48	03/20/24	DST	
4031331-18	Sample Location: 22070000-018IM/ Maintenance Shop 130 / Ice Machine									
Lead (‡)		1030	ND	ppb	1.0	15	03/06/24 06:49	03/20/24	DST	
4031331-19	Sample Location: 22070000-019SF/ Maintenance Shop 130 / Staff Sink									
Lead (‡)		1030	ND	ppb	1.0	15	03/06/24 06:49	03/20/24	DST	
4031331-20	Sample Location: 22070000-020BF/ 106 Boy's Restroom-Downstairs / Bathroom Sink #1									
Lead (‡)		1030	2.2	ppb	1.0	15	03/06/24 06:51	03/20/24	DST	
4031331-21	Sample Location: 22070000-021BF/ 106 Boy's Restroom-Downstairs / Bathroom Sink #2									
Lead (‡)		1030	8.2	ppb	1.0	15	03/06/24 06:51	03/20/24	DST	
4031331-22	Sample Location: 22070000-022BF/ 108 Girl's Restroom-Downstairs / Bathroom Sink									
Lead (‡)		1030	ND	ppb	1.0	15	03/06/24 06:52	03/20/24	DST	
4031331-23	Sample Location: 22070000-023BF/ Staff Breakroom Restroom 207 / Bathroom Sink Hot									
Lead (‡)		1030	ND	ppb	1.0	15	03/06/24 06:41	03/20/24	DST	

UMPQUA Research Company/MC

The results in this report apply to the samples analyzed in accordance with the chain of custody document.

This analytical report must be reproduced in its entirety.


Dan Phillips, Laboratory Manager



UMPQUA Research Company

626 NE Division St. - P.O. Box 609
Myrtle Creek, Oregon 97457
(541) 863-5201 Fax: (541) 863-6199
E-mail: Lab@URCmail.net
Internet: <http://ChemLab.cc>
ORELAP ID# OR100031

ANALYSIS REPORT

URC # 4031331

Qualifiers and Definitions

DET	Analyte DETECTED
ND	Analyte NOT DETECTED at or above the MRL (minimum reporting limit)
NA	Not Applicable
NR	Not Reported
dry	Sample results reported on a dry weight basis
RPD	Relative Percent Difference
MRL	Minimum Reporting Limit
MDL	Minimum Detection Limit
MCL	Maximum Contamination Level
(‡)	ORELAP Accredited Analyte
(~)	Due to rounding of individual analytes, the "total" may vary slightly from the sum of the individual analyte values.

UMPQUA Research Company/MC

The results in this report apply to the samples analyzed in accordance with the chain of custody document.

This analytical report must be reproduced in its entirety.

Dan Phillips, Laboratory Manager