

UMPQUA Research Company

626 NE Division St. - P.O. Box 609
 Myrtle Creek, Oregon 97457
 (541) 863-5201 Fax: (541) 863-6199
 E-mail: Lab@URCmail.net
 Internet: http://ChemLab.cc
 ORELAP ID# OR100031

ANALYSIS REPORT

URC # 9080122

Pendleton School District 107 NW 10th Street Pendleton, OR 97801	Project: General Project #: Lead Testing 2019/PHS Client Contact: Michelle Jones	Date Reported: 08/27/19 Date Received: 08/01/19 11:00 Sampled By: KLL
--	--	---

Method: EPA 200.8

Matrix: Drinking Water


	Sample Location	Code	Result	Units	MRL	MCL	Sampled	Analyzed	Analyst	Qualifier
9080122-01	Sample Location: Track Concessions Building Restroom Sink-1/PSD 105									
Lead (¢)		1030	4	ppb	2	15	07/24/19 13:38	08/14/19	TWW	
9080122-02	Sample Location: Track Concessions Building Restroom Sink-2/PSD 106									
Lead (¢)		1030	ND	ppb	2	15	07/24/19 13:40	08/14/19	TWW	
9080122-03	Sample Location: Track Concessions Building Restroom Sink-3/PSD 107									
Lead (¢)		1030	ND	ppb	2	15	07/24/19 13:40	08/14/19	TWW	
9080122-04	Sample Location: Babe Ruth Restrooms Sink-3/PSD 108									
Lead (¢)		1030	ND	ppb	2	15	07/24/19 14:00	08/14/19	TWW	
9080122-05	Sample Location: Babe Ruth Restrooms Sink-1/PSD 109									
Lead (¢)		1030	11	ppb	2	15	07/24/19 14:01	08/14/19	TWW	
9080122-06	Sample Location: Babe Ruth Restrooms Sink-2/PSD 110									
Lead (¢)		1030	2	ppb	2	15	07/24/19 14:02	08/14/19	TWW	
9080122-07	Sample Location: Babe Ruth Restrooms Sink-3/PSD 111									
Lead (¢)		1030	16	ppb	2	15	07/24/19 14:02	08/14/19	TWW	CON-1
9080122-08	Sample Location: Babe Ruth Restrooms Sink-4/PSD 112									
Lead (¢)		1030	7	ppb	2	15	07/24/19 14:02	08/14/19	TWW	
9080122-09	Sample Location: Football Field Hose Bib/PSD 113									
Lead (¢)		1030	ND	ppb	2	15	07/24/19 14:25	08/14/19	TWW	
9080122-10	Sample Location: Freshman Football Field Hose Bib/PSD 114									
Lead (¢)		1030	4	ppb	2	15	07/25/19 06:12	08/14/19	TWW	
9080122-11	Sample Location: Hitting Facility Girls Restroom Sink/PSD 115									
Lead (¢)		1030	ND	ppb	2	15	07/25/19 13:59	08/14/19	TWW	
9080122-12	Sample Location: Hitting Facility Boys Restroom Sink/PSD 116									
Lead (¢)		1030	14	ppb	2	15	07/25/19 06:50	08/14/19	TWW	

UMPQUA Research Company/MC

The results in this report apply to the samples analyzed in accordance with the chain of custody document.

This analytical report must be reproduced in its entirety.

Tom Williams, Laboratory Manager



UMPQUA Research Company

626 NE Division St. - P.O. Box 609
 Myrtle Creek, Oregon 97457
 (541) 863-5201 Fax: (541) 863-6199
 E-mail: Lab@URCmail.net
 Internet: http://ChemLab.cc
 ORELAP ID# OR100031

ANALYSIS REPORT

URC # 9080122

Method: EPA 200.8

Matrix: Drinking Water


	Sample Location	Code	Result	Units	MRL	MCL	Sampled	Analyzed	Analyst	Qualifier
9080122-13	Sample Location: Hitting Facility Drinking Fountain/PSD 117									
Lead (¢)		1030	ND	ppb	2	15	07/25/19 13:47	08/14/19	TWW	
9080122-14	Sample Location: Room 104 (Building 4 Ag) Sink/PSD 118									
Lead (¢)		1030	ND	ppb	2	15	07/25/19 08:02	08/14/19	TWW	
9080122-15	Sample Location: Room 118 Girls Restroom (Building 4) Sink-1/PSD 119									
Lead (¢)		1030	ND	ppb	2	15	07/25/19 08:05	08/14/19	TWW	
9080122-16	Sample Location: Room 118 Girls Restroom (Building 4) Sink-2/PSD 120									
Lead (¢)		1030	ND	ppb	2	15	07/25/19 08:05	08/14/19	TWW	
9080122-17	Sample Location: Room 121 Boys Restroom (Building 4) Sink-1/PSD 121									
Lead (¢)		1030	2	ppb	2	15	07/25/19 08:07	08/14/19	TWW	
9080122-18	Sample Location: Room 121 Boys Restroom (Building 4) Sink-2/PSD 122									
Lead (¢)		1030	ND	ppb	2	15	07/25/19 08:07	08/14/19	TWW	
9080122-19	Sample Location: Room 204 Girls Restroom (First Floor by Lifeskills) Sink/PSD 123									
Lead (¢)		1030	ND	ppb	2	15	07/25/19 08:37	08/14/19	TWW	
9080122-20	Sample Location: Room 203 Boys Restroom (First Floor by Lifeskills) Sink/PSD 124									
Lead (¢)		1030	12	ppb	2	15	07/25/19 08:37	08/14/19	TWW	
9080122-21	Sample Location: Room 224 (Lifeskills) Restroom Sink/PSD 125									
Lead (¢)		1030	ND	ppb	2	15	07/25/19 08:48	08/14/19	TWW	
9080122-22	Sample Location: Room 216 (Daycare) Restroom Sink-1/PSD 126									
Lead (¢)		1030	4	ppb	2	15	07/25/19 08:51	08/14/19	TWW	
9080122-23	Sample Location: Room 216 (Daycare) Restroom Sink-2/PSD 127									
Lead (¢)		1030	ND	ppb	2	15	07/25/19 08:55	08/14/19	TWW	
9080122-24	Sample Location: Room 211 (Staff Workroom) Restroom Sink-1/PSD 128									
Lead (¢)		1030	ND	ppb	2	15	07/25/19 09:02	08/14/19	TWW	
9080122-25	Sample Location: Room 211 (Staff Workroom) Restroom Sink-2/PSD 129									
Lead (¢)		1030	ND	ppb	2	15	07/25/19 09:01	08/14/19	TWW	
9080122-26	Sample Location: Room 211 (Staff Workroom) Sink/PSD 130									
Lead (¢)		1030	7	ppb	2	15	07/25/19 09:00	08/14/19	TWW	
9080122-27	Sample Location: Room 307 Women's Restroom (Office) Sink/PSD 131									

UMPQUA Research Company/MC

The results in this report apply to the samples analyzed in accordance with the chain of custody document.

This analytical report must be reproduced in its entirety.

Tom Williams, Laboratory Manager



UMPQUA Research Company

626 NE Division St. - P.O. Box 609
 Myrtle Creek, Oregon 97457
 (541) 863-5201 Fax: (541) 863-6199
 E-mail: Lab@URCmail.net
 Internet: http://ChemLab.cc
 ORELAP ID# OR100031

ANALYSIS REPORT

URC # 9080122

Method: EPA 200.8

Matrix: Drinking Water


	Sample Location	Code	Result	Units	MRL	MCL	Sampled	Analyzed	Analyst	Qualifier
Lead (±)		1030	ND	ppb	2	15	07/25/19 09:05	08/14/19	TWW	
9080122-28	Sample Location: Room 308 Men's Restroom (Office) Sink/PSD 132									
Lead (±)		1030	ND	ppb	2	15	07/25/19 09:04	08/14/19	TWW	
9080122-29	Sample Location: Room 311 Health Restroom (Office) Sink/PSD 133									
Lead (±)		1030	ND	ppb	2	15	07/25/19 09:06	08/14/19	TWW	
9080122-30	Sample Location: Room 407 Warberg Girls Locker Room- Restroom Sink/PSD 134									
Lead (±)		1030	ND	ppb	2	15	07/25/19 07:44	08/14/19	TWW	
9080122-31	Sample Location: Room 408 Warberg Girls Locker Room Office- Restroom Sink/PSD 135									
Lead (±)		1030	ND	ppb	2	15	07/25/19 07:43	08/14/19	TWW	
9080122-32	Sample Location: Room 422 Warberg Boys Locker Room- Restroom Sink/PSD 136									
Lead (±)		1030	3	ppb	2	15	07/25/19 07:39	08/14/19	TWW	
9080122-33	Sample Location: Room 422 Warberg Boys Locker Room Office- Restroom Sink/PSD 137									
Lead (±)		1030	ND	ppb	2	15	07/25/19 07:41	08/15/19	TWW	
9080122-34	Sample Location: Room 514 Girls Restroom (2nd Floor by the Buck Stop) Restroom Sink/PSD 138									
Lead (±)		1030	21	ppb	2	15	07/25/19 07:58	08/15/19	TWW	CON-1
9080122-35	Sample Location: Room 513 Boys Restroom (2nd Floor by the 4 Corners) Restroom Sink/PSD 139									
Lead (±)		1030	2	ppb	2	15	07/25/19 07:57	08/15/19	TWW	
9080122-36	Sample Location: Room 531 Girls Restroom (2nd Floor by Warberg) Restroom Sink/PSD 140									
Lead (±)		1030	ND	ppb	2	15	07/25/19 07:52	08/15/19	TWW	
9080122-37	Sample Location: Room 530 Boys Restroom (2nd Floor by Warberg) Restroom Sink/PSD 141									
Lead (±)		1030	15	ppb	2	15	07/25/19 07:53	08/15/19	TWW	CON-1
9080122-38	Sample Location: Room 625 Library Workroom Sink/PSD 142									
Lead (±)		1030	ND	ppb	2	15	07/25/19 08:11	08/15/19	TWW	
9080122-39	Sample Location: Room 704 Girls Restroom (Commons) Restroom Sink-1/PSD 143									
Lead (±)		1030	ND	ppb	2	15	07/25/19 08:33	08/15/19	TWW	
9080122-40	Sample Location: Room 704 Girls Restroom (Commons) Restroom Sink-2/PSD 144									
Lead (±)		1030	ND	ppb	2	15	07/25/19 08:34	08/15/19	TWW	
9080122-41	Sample Location: Room 705 Boys Restroom (Commons) Restroom Sink-1/PSD 145									
Lead (±)		1030	ND	ppb	2	15	07/25/19 08:34	08/15/19	TWW	

UMPQUA Research Company/MC

The results in this report apply to the samples analyzed in accordance with the chain of custody document.

This analytical report must be reproduced in its entirety.

Tom Williams, Laboratory Manager



UMPQUA Research Company

626 NE Division St. - P.O. Box 609
 Myrtle Creek, Oregon 97457
 (541) 863-5201 Fax: (541) 863-6199
 E-mail: Lab@URCmail.net
 Internet: http://ChemLab.cc
 ORELAP ID# OR100031

ANALYSIS REPORT

URC # 9080122

Method: EPA 200.8

Matrix: Drinking Water


	Sample Location	Code	Result	Units	MRL	MCL	Sampled	Analyzed	Analyst	Qualifier
9080122-42	Sample Location: Room 705 Boys Restroom (Commons) Restroom Sink-2/PSD 146									
Lead (¢)		1030	ND	ppb	2	15	07/25/19 09:47	08/15/19	TWW	
9080122-43	Sample Location: Room 712A Health Exam Room Sink/PSD 147									
Lead (¢)		1030	8	ppb	2	15	07/25/19 08:28	08/15/19	TWW	
9080122-44	Sample Location: Room 913 Girls Restroom (3rd Floor East Side) Sink/PSD 148									
Lead (¢)		1030	ND	ppb	2	15	07/25/19 08:23	08/15/19	TWW	
9080122-45	Sample Location: Room 912 Boys Restroom (3rd Floor East Side) Sink/PSD 149									
Lead (¢)		1030	4	ppb	2	15	07/25/19 08:22	08/15/19	TWW	
9080122-46	Sample Location: Room 930 Girls Restroom (3rd Floor West Side) Sink/PSD 150									
Lead (¢)		1030	5	ppb	2	15	07/25/19 08:19	08/15/19	TWW	
9080122-47	Sample Location: Room 929 Boys Restroom (3rd Floor West Side) Sink/PSD 151									
Lead (¢)		1030	ND	ppb	2	15	07/25/19 08:20	08/15/19	TWW	
9080122-48	Sample Location: Room 1110 Team Dressing Room Gold Gym Restroom Sink-1/PSD 152									
Lead (¢)		1030	39	ppb	2	15	07/25/19 09:38	08/15/19	TWW	CON-1
9080122-49	Sample Location: Room 1110 Team Dressing Room Gold Gym Restroom Sink-2/PSD 153									
Lead (¢)		1030	26	ppb	2	15	07/25/19 09:38	08/15/19	TWW	CON-1
9080122-50	Sample Location: Room 1117 Team Dressing Room Gold Gym Restroom Sink-1/PSD 154									
Lead (¢)		1030	32	ppb	2	15	07/25/19 09:35	08/15/19	TWW	CON-1
9080122-51	Sample Location: Room 1117 Team Dressing Room Gold Gym Restroom Sink-2/PSD 155									
Lead (¢)		1030	17	ppb	2	15	07/25/19 09:35	08/15/19	TWW	CON-1
9080122-52	Sample Location: Room 1144 Girls Restroom Gold Gym Upstairs Restroom Sink-1/PSD 156									
Lead (¢)		1030	ND	ppb	2	15	07/25/19 09:34	08/15/19	TWW	
9080122-55	Sample Location: Room 1146 Boys Restroom Gold Gym Upstairs Restroom Sink-2/PSD 159									
Lead (¢)		1030	ND	ppb	2	15	07/25/19 09:34	08/15/19	TWW	
9080122-56	Sample Location: Room 1143 Gold Gym Upstairs East Side Drinking Fountain/PSD 160									
Lead (¢)		1030	ND	ppb	2	15	07/25/19 09:33	08/15/19	TWW	
9080122-57	Sample Location: Room 1212 Womens Restroom Bld 6 Sink/PSD 161									
Lead (¢)		1030	11	ppb	2	15	07/25/19 09:11	08/15/19	TWW	

UMPQUA Research Company/MC

The results in this report apply to the samples analyzed in accordance with the chain of custody document.

This analytical report must be reproduced in its entirety.

Tom Williams, Laboratory Manager



UMPQUA Research Company

626 NE Division St. - P.O. Box 609
 Myrtle Creek, Oregon 97457
 (541) 863-5201 Fax: (541) 863-6199
 E-mail: Lab@URCmail.net
 Internet: http://ChemLab.cc
 ORELAP ID# OR100031

ANALYSIS REPORT

URC # 9080122

Method: EPA 200.8

Matrix: Drinking Water


	Sample Location	Code	Result	Units	MRL	MCL	Sampled	Analyzed	Analyst	Qualifier
9080122-58	Sample Location: Room 1212 Womens Restroom Bld 6 Sink-2/PSD 162									
Lead (¢)		1030	14	ppb	2	15	07/25/19 09:11	08/15/19	TWW	
9080122-59	Sample Location: Room 1212 Womens Restroom Bld 6 Sink-3/PSD 163									
Lead (¢)		1030	13	ppb	2	15	07/25/19 09:11	08/15/19	TWW	
9080122-60	Sample Location: Room 1219 Men's Restroom Bld 6 Sink-1/PSD 164									
Lead (¢)		1030	4	ppb	2	15	07/25/19 09:13	08/15/19	TWW	
9080122-61	Sample Location: Room 1219 Men's Restroom Bld 6 Sink-2/PSD 165									
Lead (¢)		1030	3	ppb	2	15	07/25/19 09:13	08/15/19	TWW	
9080122-62	Sample Location: Room 1219 Men's Restroom Bld 6 Sink-3/PSD 166									
Lead (¢)		1030	15	ppb	2	15	07/25/19 09:13	08/15/19	TWW	CON-1
9080122-63	Sample Location: Room 1240 Dressing Room Restroom Sink/PSD 167									
Lead (¢)		1030	ND	ppb	2	15	07/25/19 09:15	08/15/19	TWW	
9080122-64	Sample Location: Room 1241 Dressing Room Restroom Sink/PSD 168									
Lead (¢)		1030	ND	ppb	2	15	07/25/19 09:15	08/15/19	TWW	
9080122-65	Sample Location: Nurses Station Sink/PSD 169									
Lead (¢)		1030	ND	ppb	2	15	07/24/19 08:28	08/15/19	TWW	
9080122-66	Sample Location: McKay-Room 144 Sink/PSD 170									
Lead (¢)		1030	7	ppb	2	15	07/30/19 08:23	08/15/19	TWW	
9080122-67	Sample Location: McKay-Room 145 Sink/PSD 171									
Lead (¢)		1030	16	ppb	2	15	07/30/19 08:24	08/15/19	TWW	CON-1
9080122-68	Sample Location: McKay-Room 152 Sink/PSD 172									
Lead (¢)		1030	13	ppb	2	15	07/30/19 08:27	08/15/19	TWW	
9080122-69	Sample Location: McKay-Room 111 Sink/PSD 173									
Lead (¢)		1030	5	ppb	2	15	07/30/19 08:38	08/15/19	TWW	
9080122-70	Sample Location: SMS-Room 1067 Sink/PSD 174									
Lead (¢)		1030	26	ppb	2	15	07/30/19 09:15	08/15/19	TWW	CON-1

UMPQUA Research Company/MC

The results in this report apply to the samples analyzed in accordance with the chain of custody document.

This analytical report must be reproduced in its entirety.

Tom Williams, Laboratory Manager



UMPQUA Research Company

626 NE Division St. - P.O. Box 609
Myrtle Creek, Oregon 97457
(541) 863-5201 Fax: (541) 863-6199
E-mail: Lab@URCmail.net
Internet: <http://ChemLab.cc>
ORELAP ID# OR100031

ANALYSIS REPORT

URC # 9080122

Qualifiers and Definitions

CON-1	Results confirmed by duplicate analysis.
DET	Analyte DETECTED
ND	Analyte NOT DETECTED at or above the MRL (minimum reporting limit)
NA	Not Applicable
NR	Not Reported
dry	Sample results reported on a dry weight basis
RPD	Relative Percent Difference
MRL	Minimum Reporting Limit
MDL	Minimum Detection Limit
MCL	Maximum Contamination Level
(‡)	ORELAP Accredited Analyte
(~)	Due to rounding of individual analytes, the "total" may vary slightly from the sum of the individual analyte values.

UMPQUA Research Company/MC

The results in this report apply to the samples analyzed in accordance with the chain of custody document.

This analytical report must be reproduced in its entirety.

Tom Williams, Laboratory Manager