

Test Kit Placement Log

Name & Physical Address of School Being Tested: Pendleton Early Learning Center - 455 SW 13th Street, Pendleton, OR 97801

Building: Main Building

Radon Testing Contact at School: Ken Lebsock, 541.966.3268

Name of Individual(s) Performing Testing:

klebsock@pendletonsd.org

Logger: Ken Lebsock

Placer: Ken Lebsock

Room Description (per Floor Plan)	Canister serial #	Date Opened	Time Opened	Date Closed	Time Closed	Type of Test D=detector kit	Test Results
127	4420510	3/1/2021	6:26 AM	3/4/2021	6:28 AM	Blank	<0.4 pCi/L
127	4420509	3/1/2021	6:26 AM	3/4/2021	6:28 AM	Duplicate	2.2 pCi/L
127	4420508	3/1/2021	6:26 AM	3/4/2021	6:28 AM	D	2.1 pCi/L
127	4420511	3/1/2021	6:26 AM	3/4/2021	6:28 AM	Spike	9.9 pCi/L

NELAC NY 11769
NRPP 103216 AL
NRSB ARL0017

EPA Method #402-R-92-004
Liquid Scintillation
NRPP Device Code 8088
NRSB Device Code 12193

Laboratory Report for:

Property Tested:

Not Indicated

Pendleton Early Learning Center
455 Southwest 13th Street
Pendleton OR 97801


Log Number	Device Number	Test Exposure	Duration:	Area Tested	Result pCi/L
2862453	4420510	03/01/2021 6:26 am	03/04/2021 6:28 am	Room 127	< 0.4
2862454	4420509	03/01/2021 6:26 am	03/04/2021 6:28 am	Room 127	2.2
2862455	4420508	03/01/2021 6:26 am	03/04/2021 6:28 am	Room 127	2.1
2862456	4420511	03/01/2021 6:26 am	03/04/2021 6:28 am	Room 127	9.9

Comment: A copy of this report was emailed to klebsock@pendletonsd.org.

Test Performed By: Placed: Ken Lebsock Retrieved: Ken Lobsock

Distributed by: Inspect USA

Date Received: 03/05/2021 Date Logged: 03/05/2021 Date Analyzed: 03/06/2021 Date Reported: 03/08/2021

Report Reviewed By: 

Report Approved By: 

Shawn Price, Director of Laboratory Operations, AccuStar Labs

Disclaimer:

The uncertainty of this radon measurement is +/- 10%. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.